

Division of Oil, Gas, & Mining Mining Report

01/02/96

MINE ID: S0190022

MINE NAME: ORO #17 AND ORO #20

BLM #:

OPERATOR: ADAMS, JOHN CONTACT: JOHN ADAMS

ADDRESS: 130 SOUTH 3RD EAST, APT.

BOX 611

MOAB UT 84532 PHONE: (801)259-4907

Surface Owner: BLM

Lease #: Mineral Owner: BLM

Sec Town Range 25 25.0S 23.0E 26 25.0S 23.0E Qtr-Qtr-Qtr1 Qtr-Qtr1 Qtr1 Qtr-Qtr2 Qtr-Qtr2 Qtr2 sw sw

Mine Type [(S)urface, (U)nderground]: S Permit Status: APP

Acreage: Mine Status: SUS

Status Date: / /

Minerals Mined

DATE TENTATIVE APPROVAL FINAL APPROVAL LAST INSPECTED DATE DATE RECEIVED 01/12/91 10/10/89 11/24/89 11/24/89

BOND TYPE: N/A BOND AMOUNT:

ANNUAL REPORT YEAR: 95

YTD Total NONCOMP NOTICES: 0 0 DATE ISSUED: / /
VIOLATIONS: 0 0 DATE ISSUED: / /
REVISIONS: 0 0 DATE REC'D: / /
AMENDMENTS: 0 0 DATE REC'D: / / DATE RESOLVED: DATE RESOLVED: DATE APPROVED: DATE APPROVED:

COMMENTS:

NO DISTURBANCE AT THE SITE AS YET. TWO OR THREE PITS PROPOSED. POND ALREADY EXISTS ON SITE, BUT IS DRY AND WAS FED BY A SPRING. PIPES LEADING TO SPRING ARE NON FUNCTIONAL. ANNUAL REPORT FOR 1990 STATES THAT SAMPLING & FEASABILITY STUDY NEARLY DONE. WILL WORK ON METHOD OF PROCESSING & MARKETING PRODUCT. 1992 REPORT STATED THAT ONLY TESTING IS BEING DONE. CUTTING SMALL SAMPLES & DOING METALURGICAL WORK TO DETERMINE FLOW SHEET. 95 REPORT STATES BLM REFUSED TO PERMIT OPERATION. DROPPED CLAIMS. MAY FILE LATER ON STATE SECTIONS.